

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

AP242  
SW  
1/4-1/2  
0.357 mi.  
1885 ft.

APT BLDG  
1608 MERMAID AVE  
BROOKLYN, NY  
Site 4 of 4 in cluster AP

NY Spills S109582848  
N/A

Relative:  
Higher

Actual:  
5 ft.

SPILLS:

Name: APT BLDG  
Address: 1608 MERMAID AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0901790 / 2009-08-06  
Facility ID: 0901790  
Facility Type: ER  
DER Facility ID: 362922  
Site ID: 413803  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2009-05-13  
Investigator: SFRAHMAN  
Referred To: Not reported  
Reported to Dept: 2009-05-13  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2009-05-13  
Spill Record Last Update: 2009-08-06  
Spiller Name: Not reported  
Spiller Company: APT BLDG  
Spiller Address: 1608 MERMAID AVE  
Spiller Company: 999  
Contact Name: CHRISTINE MAZZARELLA  
DEC Memo: "Sangesland spoke to Christine and Jim at Associated Environmental.

They said the levels were only slightly over the limit and they're hoping the case can be closed out. They will fax over the test results today and ask Sharif Rahman to review the results and call them back. No CSL letter was sent out. 08/06/09 Rec'd tank closure report. Soil and ground water samples were taken from the abandoned tankfield. The 550 gallon UST was closed in place with sand in it. Earlier tank contents were removed and disposal manifests are provided. Residual contamination in soil and ground water minimal. Reports in edocs.(sr)"

Remarks: "PHASE 2 RESULTS AROUND A FORMER UST. CONTAMINATED SOIL AND GROUNDWATER. CLEAN UP IS PENDING."

All Materials:

Site ID: 413803  
Operable Unit ID: 1170211  
Operable Unit: 01  
Material ID: 2161931  
Material Code: 0066A  
Material Name: unknown petroleum

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported